



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 25, 2007

Supervisor DBZ

Mine Name: Green Beetle Quarry
Operator Name: Bonneville Quarries, Inc.

Permit number: S/003/017
Inspection Date: April 11, 2007
Time: 9:00 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none
Mine Status: Permitted, No activity yet this season

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine inspection while in the area.

Inspection Summary:
Last fall, the operator had called the Division to notify us of the intent to transfer this operation to Royce Larsen, and requested that bonding requirements be extended until the transfer was completed (the new operator would then be providing the reclamation surety). On March 12, 2007, a letter was sent to the operator requiring him to provide the reclamation surety (The Division has not received a transfer request for this operation). This letter also informed the operator that there is to be no activity on the site until the surety is in place.

There is no equipment on site. There has apparently been no activity this year. Operator is now in the process of providing the requisite surety and reclamation contract.

Photos were taken to document site conditions.

Conclusions and Recommendations:
Continue to monitor this site when in the area.

Inspector's Signature LK

LK:pb

O:\M003-BoxElder\S0030017-GreenBeetle\inspections\Insp-04112007.doc